







W 15



a1  8x35 x....(x8)	d2  x....(x8)	e0  x....(x8)	e1  x....(x8)	f1  x....(x8)	i5  3.5x30 x....(x4)	m  x....(x1)	n1  3x16 x....(x5)	p8  x....(x1)	r4  x....(x6)
---	---	---	---	---	---	---	---	---	---



- ① -C1
- ② -C1
- ③ -C1
- ④ -C1

